

Suite 2.06, Level 2 29-31 Solent Circuit Norwest NSW 2153

Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

Healthy Buildings International Pty LtdA.C.N. 003 270 693A.B.N. 39 003 270 693

Mr Rob Sherry Team Leader Compliance – Government Projects Department of Planning Industry and Environment GPO Box 39 SYDNEY NSW 2001

4 March 2020 Ref: 170108-ER-DPIE-TSE-MP-VC-20

Dear Rob

RE: Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 – ER Monthly Report for February 2020 – TSE , Martin Place ISD, Victoria Cross ISD

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 Approval (9 January 2017) and associated modifications MOD1_Victoria Cross and Artarmon (18 October 2017), MOD2_Central Walk (21 December 2017), MOD4_Sydenham Station and Metro Facility South (13 December 2017), MOD 3_ Martin Place Metro Station (22 March 2018), MOD5_Blues Point Acoustic Shed (2 November 2018), and MOD6_Administrative Changes (21 February 2019); and
- As required by the subsequent appointment as the approved Environmental Representative (17 February 2017);

The attached summary details the key activities undertaken by Environmental Representatives for Sydney Metro – City and South West Chatswood to Sydenham during the month of **February 2020**.

Yours sincerely

Michael Woolley Environmental Representative

Cc: Sydney Metro: Fil Cerone, Matt Marrinan, Ben Armstrong, Hugh Chapman, Adam Koutsamanis, Pam Tummers, Ann Paterson, Contractors: Rob Muir (JHCPBG), Jason Ambler (LL) DPIE: Rob Sherry, Elizabeth Williamson, Alice Pryke, Erica Van Den Honert CC IEA: Larry Weiss, Julie Dickson

Summary of Contract Packages		Environmental Representative/s	
Tunnel and Station Excavation (TSE)		Michael Woolley	
Martin Place Unsolicited Proposal USP/ISD Macquarie Bank/Lend		Michael Woolley/Jo Robertson	
Lease			
Victoria C	ross ISD (VC-ISD) - Lend Lease	Michael Woolley/Jo Robertson	
Key Const	ruction Activities		
TSE	Chatswood:		
	 Works in the dive continuing including st 		
	demobilisation of tunnelling infrastructure inclu	uding removal of conveyors and grout plant.	
	Chatswood NCW:		
	 Brand Street works - wall support complet 		
	stabilised DGB gravel access under construction.		
	Victoria Cross North site:		
	 Ongoing works in the cavern including concrete 	e lining.	
	 Hammering of base of shaft ongoing. Stackpilling and load out of anall by trucks and 	ine	
	 Stockpiling and load out of spoil by trucks ongo Water treatment plant operation. 	ing.	
	 Concrete deliveries for concrete pours. 		
	Victoria Cross South site:		
	 Demolition of the acoustic shed completed. 		
	 Preparation for piling works. 		
	 Support activities. 		
	Blues Point Temporary:		
	 TBM retrieval works completed. 		
	 Preparation to hand site internally to JHCPBG B 	arangaroo team.	
	 Ongoing load out of items onto trucks. 	-	
	Martin Place Station-South:		
	 Ongoing excavation of the pedestrian adit; rem 	oval of spoil using kibble and crane;	
	excavation of shaft to the ESR using small road	header (24/7 operation).	
	Marrickville dive site:		
	 Demobilisation of tunnelling infrastructure inclusion 	uding demolition of the acoustic spoil sheds	
	grout plant; workshops and conveyors.		
	 Ongoing excavation in the dive. 		
	 Ongoing Transgrid works. WTP operational. 		
	Marrickville precast facility		
	 Site undergoing excavation for stabling yard. 		
	Cranes broken up for scrap; stockpiled and rem		
	 Pre-cast facility demobilised and being demolis Concrete slob and facting removal 	ned.	
	 Concrete slab and footing removal. Piling along the side of the culvert to support exists. 	victing outport	
	Thing doing the side of the curvert to support e	xisting cuivert.	
	Management and removal of scrap materials.	ring excavation activities	
	 Removal of underground tanks encountered during excavation activities. Pitt Street North: 		
	 Excavation of shaft outside the acoustic shed and 	nd wall support	
	 Spoil management and removal off site. 		
	Pitt Street South:		
	 Excavation and wall support continuing. 		
	 Shear wall construction ongoing. 		
	Waterloo:		
	 Tunnelling personnel established on site as bas 	e for cross passage excavation and other	
	tunnelling activities.		
	 Concrete delivery using chute. 		
	 laydown for plant and equipment. 		

HBI Healthy Buildings International Pty Ltd

	 removal of spoil. 	
	Barangaroo Station:	
	 TBM 5 and slurry plant operating. TBM5 completed tunnelling in harbour sediments. 	
	operation of the water deathert plant.	
	harbour seament (dela sulphate sons) was removed for an eet onsite disposal.	
	 Lining of station box ongoing. Concrete slab in base of station box being constructed. Installation of anchors in the shark's fin area. 	
MP –		
USP/ISD	 Sandstone being excavated at depth by rock hammer in northern section of the excavation Loading out of spoil to trucks located in the northern adit exiting site at Bligh Street 	
038/130	compound.	
	 Roof support over adits within the excavation. 	
VC-ISD	 Utility investigation activities during out of hours. 	
VC-13D	- Other investigation activities during out of nours.	
ER Inspectio	ons	
TSE	Weekly inspections continued of the sites under the management of the TSE contractor. There	
	were four inspections carried out during the month. Issues identified during the inspections:	
	included:	
	 Marrickville Dive Site – clean up of spill in the grout plant; Secondary containment for 	
	drum; loose dirt on internal haul roads and at site exits; repair sediment fence;	
	accumulated material in gutter.	
	 Barangaroo – increase capacity of ERSED controls; minor leak of sediment laden water to wharf. 	
	 NCW Brand Street –water from boot wash to be appropriately controlled; sumps to be 	
	cleaned out; copy of ESCP for all areas to be available in Brand street site shed; ensure the	
	design of the road and ERSED controls is adequate for the access road.	
	 Blues Point – Secondary containment of small containers; re-seal bund and clean out used spill kit material. 	
	 Waterloo –provide secondary containment for IBCs; Repair hole in air line; loose dirt on hardstand at south end of the site; offensive graffiti to be removed. 	
	Various notes were made in the inspection reports reflecting commitments made by the TSE	
	Contractors and risks identified during inspections.	
	ER Inspection reports have been prepared and issued to Sydney Metro and the TSE Contractor.	
MP – USP/	There was one inspection carried out in February 2020 of Martin Place North. No new issues were	
ISD	identified during the inspection. Various notes were made in the inspection report. ER Inspection report was prepared and issued to Sydney Metro and the MP-ISD Contractor.	
VC-ISD	Nil Inspections conducted.	

Endorsed Do	Endorsed Document/s		
Sydney	 Nil this reporting period. 		
Metro			
TSE	 Marrickville SEP Revision for Stabling Yard and other works 		
	 Waterloo Station SEP Revision 		
	 OOHW for sewer works at Waterloo 		
	 OOHW for sewer works at Martin Place 		
	 OOHW for sewer works at Pitt Street 		
USP/ ISD-	 OOH28 Power switchover and pole removal 		
Martin			
Place			
VC - ISD	 OOH2 Utilities Rev 4. 		
Complaints ,	/ Incidents / Non-compliance		
TSE	It is understood that Sydney Metro has been providing summaries of complaints to DPIE		
	daily. Responses to each complaint have been noted in each complaint report provided to the ER,		
	with follow up actions often defined in revised reports.		

HBI Healthy Buildings International Pty Ltd

	There were no incidents reported by JHCPBG as defined by the project approval definition for		
	incidents under condition A41.		
	Planning Approval Condition C15 requires construction monitoring programs are implemented		
	during construction. The Surface Water Monitoring Program requires sampling from the Water		
	Treatment Plants (WTPs) to be conducted at the time of undertaking monitoring at the surface		
	water locations listed in Table 10 of Soil, Water and Groundwater Management Plan. Testing		
	required from the WTP included iron, manganese, pH, TSS and oil and grease. A recent review has		
	identified that not all analytes were always being tested from the WTPs during the surface water		
	monitoring events.		
USP/ ISD-	No complaints were reported to the ER that related to the MP-ISD project.		
Martin	There were no incidents reported by Lend Lease as defined by the project approval definition for		
Place	incidents under condition A41.		
	Lend Lease informed the project on 17 February 2020 of an exceedance of vibration screening		
	criterion defined in Condition E28.1 when hammering adjacent 50 Martin Place. Work methods		
	were reported by Lend Lease to have been adjusted to avoid further exceedance of the screening		
	criterion.		
Sydney	Complaints received for Sydney Metro works are included in complaint summaries provided to DPIE		
Metro	daily.		
	There were no incidents reported by Sydney Metro for Sydney Metro conducted works as defined		
	by the project approval definition for incidents reported to DPIE under condition A41.		
Audits (spec	ific to TSE, MP ISD , and VIC ISD only)		
	g audits relevant to this report, were conducted during the period:		
■ ER a	and Audit Meeting – 14/02/2020		
Disc	cussion Audit findings and resolution to close out audit actions – 21/02/2020		
Looking For	ward – Core Focus Areas		
TSE	 Water treatment plant and discharge at Barangaroo 		
	 Management of spoil from under harbour tunnelling at Barangaroo 		
	 ERSED controls in the Northern Corridor Area 		
MP – USP/	 Management of noise, vibration and dust during bulk excavation activities 		
ISD			
VC - ISD	■ Nil		

Statement of Limitations

Healthy Buildings International (HBI) has prepared this report in accordance with the requirements of Condition A24(I) of the Sydney Metro Conditions of Approval (CSSI15_7400). The report is for the sole purposes of Department of Planning Industry and Environment (DPIE) and Sydney Metro. It has been prepared based on generally accepted practices and standards at the time it was prepared. No other warranty, expressed or implied, is made as to the professional advice included in this Report. This report did not assess any aspects relating to safety.

Where the Report indicates that information has been provided to HBI by third parties, HBI assumes no liability for any inaccuracies in or omissions to that information.

This Report was prepared based on the conditions encountered and information reviewed at this time. HBI disclaims responsibility for any changes that may have occurred after this time.

This Report should be read in full. No responsibility is accepted for use of any part of this report in any other context or for any other purpose or by third parties. This Report does not purport to give legal advice. Legal advice can only be given by qualified legal practitioners.

Except as required by law, no third party may use or rely on this Report unless otherwise agreed by HBI in writing. Except as specifically stated in this section, HBI does not authorise the use or findings of this Report by any third party

To the extent permitted by law, HBI expressly disclaims and excludes liability for any loss, damage, cost or expenses suffered by any third party relating to or resulting from the use of, or reliance on, any information contained in this Report. HBI does not admit that any action, liability or claim may exist or be available to any third party.