

Suite 2.06, Level 2 29-31 Solent Circuit Norwest NSW 2153

Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

Healthy Buildings International Pty LtdA.C.N. 003 270 693A.B.N. 39 003 270 693

Mr Rob Sherry Team Leader Compliance – Government Projects Department of Planning Industry and Environment GPO Box 39 SYDNEY NSW 2001

6 February 2020 Ref: 170108-ER-DPIE-TSE-MP-VC-20

Dear Rob

RE: Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 – ER Monthly Report for January 2020 – TSE , Martin Place ISD, Victoria Cross ISD

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

- Condition A24 (I) of the Sydney Metro City & South West Chatswood to Sydenham CSSI 15_7400 Approval (9 January 2017) and associated modifications MOD1_Victoria Cross and Artarmon (18 October 2017), MOD2_Central Walk (21 December 2017), MOD4_Sydenham Station and Metro Facility South (13 December 2017), MOD 3_ Martin Place Metro Station (22 March 2018), MOD5_Blues Point Acoustic Shed (2 November 2018), and MOD6_Administrative Changes (21 February 2019); and
- As required by the subsequent appointment as the approved Environmental Representative (17 February 2017);

The attached summary details the key activities undertaken by Environmental Representatives for Sydney Metro – City and South West Chatswood to Sydenham during the month of **January 2020**.

Yours sincerely

Michael Woolley Environmental Representative

Cc: Sydney Metro: Fil Cerone, Matt Marrinan, Ben Armstrong, Stuart Hodgson, Adam Koutsamanis, Pam Tummers, Ann Paterson, Contractors: Rob Muir (JHCPBG), Jason Ambler (LL) DPIE: Rob Sherry, Elizabeth Williamson, Alice Pryke, Erica Van Den Honert CC IEA: Larry Weiss, Julie Dickson

Summary	of Contract Packages	Environmental Representative/s	
Tunnel and Station Excavation (TSE)		Michael Woolley	
Martin Place Unsolicited Proposal USP/ISD Macquarie Bank/Lend Lease		Michael Woolley/Jo Robertson	
Victoria Cr	ross ISD (VC-ISD) - Lend Lease	Michael Woolley/Jo Robertson	
Key Const	ruction Activities		
TSE	Chatswood:		
	 Works in the dive continued including steel fix and conveyors removed as part of tunnelling de Chatswood NCW: Brand Street works - ongoing wall support a 	emobilisation.	
	Channon Walk was handed over to Sydney Inspections no longer required. Victoria Cross North site: Ongoing works in the cavern including conc	rete lining and formwork. Replacement of	
	Victoria Cross South site:		
	 Ongoing demolition of the acoustic shed with roof panels being removed. No access to the shed due to exclusion zone. Class B hoarding complete. 		
	 Blues Point Temporary: TBM3 and TBM4 retrieval works were ongoing and in the acoustic shed at the time of inspection 		
	 Martin Place Station-South: Roadheader activities in the pedestrian adit; re excavation of shaft to the ESR. 	moval of spoil using kibble and crane;	
	 Marrickville precast facility Pre-cast facility demobilised and concrete slab stabling yard. 	removed and site undergoing excavation for	
	Marrickville dive site:		
	 Crane setup underway. 		
	 Cross passage 25 (XP25) underway. XP27 started (validation and monitoring to CNV process of being arranged for XP28 & XP29. 	/IS), and community agreements in the	
	 Ongoing excavation in the dive. Ongoing Transgrid works. WTP operational. 		
	 Spoil removal and shed to be taken down in the XP spoil to be managed at Waterloo. 	e next few weeks.	
	 Pitt Street North: Excavation of shaft outside the acoustic shed. V 	Vall support.	
	Pitt Street South:		
	 Excavation and wall support continuing. Shear 	wall construction ongoing.	
	Barangaroo Station:		
	 TBM2 breakthrough on 16 January 2020 and re TBM1 pulled out into station box 	trieval works commenced.	
	TBM1 pulled out into station box.TBM5 had commenced tunnelling toward Blues	Point Cleaning and maintenance activition	
	at the water treatment plant ongoing.	Fount. Cleaning and mannenance activities	
	 Slurry plant operating and spoil being stored ar 	nd removed from site.	
MP –	 Sandstone being excavated at depth by rock ha 		
USP/ISD	 Spoil removal direct to haul trucks exiting through the second sec		
	 Underpinning works at 50 Martin Place. 		
	 Operation of mister at operating hammer. 		
	 Installation of sheet piling across the adit being 	held by round section piles.	

HBI Healthy Buildings International Pty Ltd

VC-ISD	 Planning for utilities investigation works. 	
ER Inspections		
TSE	Due to RDO's there were only two inspections carried out during the month. Issues identified during the inspections included:	
	 Blues Point – Obstructions in strip drain; Hydraulic oil spill clean up required. 	
	 Marrickville Dive Site – Dirt and Litter management; Erosion and Sediment Control; IBC 	
	Secondary containment.	
	Various notes were made in the inspection reports reflecting commitments made by the TSE	
	Contractors and risks identified during inspections.	
	ER Inspection reports have been prepared and issued to Sydney Metro and the TSE Contractor.	
MP – USP/	There was one inspection carried out in January 2020 of Martin Place North. No new issues were	
ISD	identified during the inspection. Various notes were made in the inspection report. ER Inspection	
	report was prepared and issued to Sydney Metro and the MP-ISD Contractor.	
VC-ISD	Nil Inspections conducted.	

Endorsed Do	ocument/s		
Sydney	 Crows Nest Utility Investigations OOH 48 		
Metro			
TSE	 OOHW Application MPS_040 Survey marker Removal scheduled 23 Jan 2020 		
USP/ ISD-	Nil		
Martin			
Place			
VC - ISD	 Victoria Cross Utility Investigations OOHW 002 		
Complaints	/ Incidents / Non-compliance		
TSE	It is understood that Sydney Metro has been providing summaries of complaints to DPIE		
	daily. Responses to each complaint have been noted in each complaint report provided to the ER,		
	with follow up actions often defined in revised reports.		
	There were no incidents reported by JHCPBG as defined by the project approval definition for		
	incidents under condition A41. Two minor hydrocarbon spill incidents and one minor spoil spill		
	incident were reported.		
	JHCPBG reported emergency works required at Victoria Cross on 29 January 2019 due to		
	mechanical issues with a crane during demobilisation of the acoustic shed. Works were completed		
	by 7:30pm and no complaints were reported due to the works.		
USP/ ISD-	No complaints were reported related to the MP-ISD project.		
Martin	There were no incidents reported by Lend Lease as defined by the project approval definition for		
Place	incidents under condition A41.		
Sydney	Complaints received for Sydney Metro works are included in complaint summaries provided to DPIE		
Metro	daily.		
	There were no incidents reported by Sydney Metro for Sydney Metro conducted works as defined		
	by the project approval definition for incidents reported to DPIE under condition A41.		
	ific to TSE, MP ISD , and VIC ISD only)		
Nil this perio			
	ward – Core Focus Areas		
TSE	 Water treatment plant and discharge at Barangaroo 		
	 Management of spoil from under harbour tunnelling at Barangaroo 		
	ERSED controls in the Northern Corridor Area and across the project in light of forecast rain		
MP – USP/ ISD	 Management of noise, vibration and dust during bulk excavation activities 		
VC - ISD	■ Nil		

Statement of Limitations

Healthy Buildings International (HBI) has prepared this report in accordance with the requirements of Condition A24(I) of the Sydney Metro Conditions of Approval (CSSI15_7400). The report is for the sole purposes of Department of Planning Industry and Environment (DPIE) and Sydney Metro. It has been prepared based on generally accepted practices and standards at the time it was prepared. No other warranty, expressed or implied, is made as to the professional advice included in this Report. This report did not assess any aspects relating to safety.

Where the Report indicates that information has been provided to HBI by third parties, HBI assumes no liability for any inaccuracies in or omissions to that information.

This Report was prepared based on the conditions encountered and information reviewed at this time. HBI disclaims responsibility for any changes that may have occurred after this time.

This Report should be read in full. No responsibility is accepted for use of any part of this report in any other context or for any other purpose or by third parties. This Report does not purport to give legal advice. Legal advice can only be given by qualified legal practitioners.

Except as required by law, no third party may use or rely on this Report unless otherwise agreed by HBI in writing. Except as specifically stated in this section, HBI does not authorise the use or findings of this Report by any third party

To the extent permitted by law, HBI expressly disclaims and excludes liability for any loss, damage, cost or expenses suffered by any third party relating to or resulting from the use of, or reliance on, any information contained in this Report. HBI does not admit that any action, liability or claim may exist or be available to any third party.