

Suite 2.06, Level 2 29-31 Solent Circuit Norwest, NSW 2153

Tel: 61 (02) 9659 5433 e-mail: <u>hbi@hbi.com.au</u> Web: www.hbi.com.au

Mr **Example** Team Leader Compliance – Government Projects Department of Planning, Housing and Infrastructure Locked Bag 5022 PARRAMATTA NSW 2124

Dear

RE: Sydney Metro City and South West – ER Monthly Reports for March 2025

Healthy Buildings International (HBI) submits this report to the Secretary in accordance with:

• Condition A26 (j) of the Sydney Metro Sydenham to Bankstown Upgrade SSI_8256 Approval (12 December 2018) and associated modifications MOD1_Bankstown Station.

The attached summaries detail the key activities undertaken by Environmental Representatives for Sydney Metro – City and South West Sydenham to Bankstown for the month of **March 2025**.

Yours sincerely

Environmental Representative

Cc: Sydney Metro: AA: Available on Sydney Metro Website Contractors: Available to Contractors on Sydney Metro Website DPHI Compliance: Portal DPHI Post Approvals: Available on Sydney Metro Website 7 April 2025 Ref: 170108-ER_DPHI Mar 2025



HBI

Healthy Buildings International Pty Ltd

Table of Contents

1.	Sydenham to Bankstown – TSOM	3
2.	Southwest Metro Corridor Package 3 (SWM3) JHLOR	4
3.	Errant and Hostile Vehicle Mitigation Treatments (EHVMT)	7
4.	Sydney Metro Retained Obligations (SM)	. 10
5.	Statement of Limitations	. 11



1. Sydenham to Bankstown – TSOM

Broject Approval	Contract Packago	EPL	Environmental			
Project Approval	Contract Package	EPL	Representative/s			
SSI 8256 (S2B)	Train Service Operation	JHLOR – MTR is working under	nepresentative/s			
	and Maintenance	JHLOR CEMP, subplans				
	(TSOM)					
Key Construction Activ	vities During the Period		I			
 Southwest corrido 	or and stations					
Installation of	field devices and associated	d cable pulls throughout Metro Se	ervice Buildings (MSBs)			
	within the station platform		0 ()			
-	mmissioning of cabinets	C C				
-	ment installation at various	locations				
Key Construction Activ	vities Look Ahead					
 Southwest corrido 	or and stations					
Marrickville, Dulwich H	ill, Hurlstone Park, Canterk	oury, Campsie, Belmore, Lakemba	, Wiley Park, Punchbowl			
and Bankstown Station	าร:					
Cable haul to t	the station platform buildin	g				
Cabinet install	ation					
 Cable haul to f 	field equipment devices					
 Installation of 	field equipment devices the	roughout the station and surround	ding areas			
 Termination of 	f cabling to field equipment	t				
 Low voltage er 	nergisation works					
 Testing and co 	mmissioning of cabinets an	nd field equipment				
ER Inspections						
	-	cable pulling were observed by th	ne ER while inspecting			
SWM3 sites, no iss	ues were raised.					
Photos						
■ N/A						
Endorsed Document/s	5					
■ Nil						
	dents or Repeat Complaint					
		omplaints to DPHI daily and a sun	•			
Responses to each complaint have been noted in each complaint report, with follow up actions often						
defined in revised reports. Key or repeat items of note are discussed below for the respective projects.						
 There were no incidents for TSOM reported to the ER under condition A36 of SSI 8256. 						
 No non-compliances were reported to the ER. 						
Project related complaints:						
 Nil 						
Unrelated Project complaints:						
• Nil						
Audits						
No audits						
Looking Forward – Core Focus Areas						
Testing and comm	Testing and commissioning between Sydenham and Bankstown					


Testing and commissioning between Sydenham and Bankstown




2. Southwest Metro Corridor Package 3 (SWM3) JHLOR

Project Approval	Contract Package	EPL	Environmental				
			Representative/s				
SSI 8256 (S2B)	Southwest Metro Corridor Package 3 (SWM3) JHLOR	#21147					
Key Construction Acti	ivities - During the Period						
	rgisation is now complete						
	ound: Site offices and amenities, fuel and gas stor	age; impleme	entation of the weed				
management plar							
	mpound, Bankstown: Site offices and amenities, fue	-	-				
	on: Roof installation complete, platform screen c	loors and m	echanical gap fillers				
	ete, platform works ongoing						
campsierriation	on: Platform screen doors and mechanical gap fille	re installation	complete platform				
works ongoing	sh. Hatiorni screen doors and mechanical gap me		r complete, plationn				
	n – Security fence installation complete, platform	screen doors	and mechanical gap				
-	complete, platform works ongoing		0-P				
	Security fence, platform screen doors and mechanic	al gap fillers i	nstallation complete,				
platform works or		0	•				
 Belmore Triangles 	Belmore Triangle: Laydown area operations ongoing including material stockpiles and concrete and						
liquid waste mana	-						
-	ity fence installation complete. Protection of heritag	ge-listed ston	e garden bed edging.				
	to the Tree Report. Platform works ongoing.						
	n: Structural steel installation complete, overhea	-					
-	mplete, tree protection and management ongoing,						
	Sydney Trains side platform works upcoming to a of laydown/work area on North Terrace. CSR works		8 cars, planning for				
	stallation, including ongoing tree impact assessmen		moval and ecologist				
-	e sections adjacent to Threatened Ecological Con		_				
	species, e.g. Breust Street ramp (Punchbowl), Urunga Parade (Punchbowl), South Terrace (Bankstown) Survey of trees in station precincts continued to verify compliance with the SPIR						
•	Archaeologist supervision within Archaeological Management Zones (AMZs), assessment of new areas						
 Ongoing operatio 	Ongoing operation of site office caravans at selected Metro Services Buildings (MSBs)						
 Stockpile manage 	Stockpile management including waste classification, waste tracking, load-in / load-out, management of						
site accesses and truck routes							
Key Construction Activities Look Ahead							
•	Survey and defect inspections at all stations						
	Bankstown Station works						
_	Testing and commissioning between Sydenham and Bankstown						
Rail possession activities at Sydney Trains side of Bankstown Station							
ER Inspections		1.0000					
There was one ER inspection conducted in the reporting period on 25 March 2025. No actions were raised							





HBI



was removed and replaced with a fodmat to further reduce the noise impact when tracked over by vehicles due to its plastic malleable properties and shallower ridges. A "Collective insights" session was held with the construction crews by the contractor to discuss preventative actions so as to avoid repeat occurrences.

There were no incidents reported to the ER under Condition A36 of SSI 8256.

There were no Class 3 environmental incidents reported to the ER during the period:

The ER is aware of the following complaints received in March 2025 related to the SWM3 works. The number of noise complaints increased mainly due to rail shutdown possession activities in this reporting period compared to the previous month:

- Four complaints related to noise and vibration (standard hours and OOHW)
- One complaint related to flora and fauna

Audits

No further ER input with regards to SWM3 audit

Summary of Environmental Performance

Environmental risks are consistent with out of hours works during possessions and maintaining compliance with the Tree Report during the security fence installation. Actions raised during ER inspections are closed out within the agreed timeframe with useful supporting documentary evidence provided.

Looking Forward – Core Focus Areas

- Management of ERSED controls generally.
- Management of noise during out-of-hours work during possessions.
- Management of tree impacts and TECs during construction of security fencing along the alignment, and maintenance of the buffer zone.
- Compliance with the planning approval for the use of land outside the project boundary, including the establishment and use of ancillary facilities.



3. Errant and Hostile Vehicle Mitigation Treatments (EHVMT)

Project Approval	Contract Package	EPL	Environmental				
			Representative/s				
SSI 8256 (S2B)	Errant and Hostile Vehicle Mitigation Treatments	No EPL					
	(EHVMT)						
	Martinus Rail						
•	ivities - During the Period						
	ngoing footpath excavation and utilities relocation						
-	Livingstone Road - All piles excavated, and concrete poured; Form Reo Pour (FRP) works underway						
	 Piling works completed, site preparation for WE3 	-	ery and placement				
	ΛP implementation, line marking and road barrier re						
	Il piles excavated, and concrete poured; FRP works	underway					
	- Piling works completed						
	Il piles excavated, concrete poured and FRP works o						
	– Footpath works near Canterbury signal hut	ongoing, wo	rks on overbridge to				
	piling works recommenced						
	fic Management Plan (TMP) implementation						
	iling works complete, barrier installation works ong	oing					
	Planning for works is ongoing						
	ite preparation works ongoing						
	d - Piling works completed, concrete pouring ongoir	-	mina				
	Punchbowl Road - TMP Stage 1 implementation, anti-throw screens removal upcoming						
	nplementation with stage 2 of hydro demolition wo	IKS					
	oncrete barrier works nearing completion						
Key Construction Act		a naura far th	o couthwast rotainin				
wall	Punchbowl – Removal of steel barriers and concret	e pours for th	e southwest retaining				
	one Park – Installation of off-structure beams (OSB)	bridge girde					
	d, Wiley Park – Installation of pre-cast barriers	bridge girder	5				
	elmore – Installation of pre-cast barriers						
	lwich Hill – Sydney Trains HV feeder 761 removal,	delivery and	installation of the off				
•	lemolition of existing balustrade fence, installation of	•					
	stone Park – Lifting of off-structure beams using cra						
	Marrickville – Remediation works, service searching						
-	arrickville - Reinstatement of existing signal pole an	-					
•	, Canterbury – Overbridge remedial works, servi		and modification of				
northeast hoardir	-						
	Loch St, Campsie – Overbridge remedial works and modification of northeast hoarding						
	Haldon St, Lakemba – Piling works on the north side of the rail corridor						
	Punchbowl Rd traffic controls implementation and anti-throw screens removal						
	Haldon St - Piling pad preparation works						
R Inspections							
	re undertaken based on scope/risk levels of the	activities. Or	ne ER inspection wa				
•	undertaken in the reporting period on 31/03/2025. No issues were raised during the inspection. Positive						
	e made regarding presence of erosion and sediment	-					





Figure 1 – Stacey St, Bankstown – Stage 2 of the hydro-demo works have been successfully completed. Site clean-up and footpath widening works in progress. Some tree branches pruning is required, arborist assessments underway.



Figure 2 – Stacey St, Bankstown – Tree trimming required to support footpath widening activities, ecologist/arborist survey to be undertaken.





Figure 3 – Brande St/Urunga Parade (non-bridge) – concrete barrier works in progress.

Figure 4 – Wardell Road – Piling completed, preparation works for girder delivery and installation in an upcoming possession.



Figure 5 – Dulwich Hill - Steel barrier works planning ongoing, Martinus to avoid all impacts to TEC/PCT in this area as per recent discussions with SM and ER. Contractor Environment Manager to discuss the potential issues with the design and construction teams.

HBI

Healthy Buildings International Pty Ltd

Endorsed Document/s

OOHW#16 – Rev A – 31/03/2025

Non-compliance/ Incidents or Repeat Complaints

Since commencement of City metro services passenger operations on Monday 19 August 2024, Sydney Metro is now providing summaries of CSW complaints on a weekly basis (was provided daily until 16 August 2024) to DPHI and ERs covering complaints related to remaining construction works.

There was one non-compliance reported to the ER during the reporting period:

13 March 2025 – A20, boundary screening as it relates to Minor Ancillary Facilities - On investigation, it was identified that boundary screening was causing pedestrian and traffic issues at Canterbury Road during inclement weather. A change notice was issued to Martinus by Sydney Metro absolving the need to place boundary screen across temporary fencing in locations where there is a potential for the screening to be blown over during inclement weather. A toolbox talk was held by the contractor to reinforce messaging. (EVT-0002104)

There were no incidents reported to the ER under Condition A36 of SSI 8256.

There was one Class 3 environmental incidents reported to the ER during the reporting period:

12/03/2025 – trespass/break in at Canterbury Signal Hut (EVT-0002105)

ER is aware of the following complaints received during the reporting period. The number of noise related complaints increased compared to the previous month due to weekend 39 possession activities:

- Three complaints related to out-of-hours noise
- One related to business impacts
- Three related to traffic, transport and parking
- One related to flora and fauna
- One related to waste management/worker behaviour

Audits

0

No ER involvement in audit activity including Independent Environmental Audits.

Looking Forward – Core Focus Areas

- Management of erosion and sediment controls generally
- Management of noise and dust during out-of-hours works
- Management and protection of retained heritage items
- Management of TECs



4. Sydney Metro Retained Obligations (SM)

Project Approval		Contract Package	EPL	Environmental Representative/s	
SSI 8256 (S2B)		Sydney Metro Retained Obligations (SM)	Not applicable		
Key Constru	ction and	other Activities			
SM	• `	Working with MTR to commen	ce dynamic testing for South	west	
ER Inspectio	ons				
	• Nil				
Endorsed Do	ocument/s	5			
SM	Nil				
Non-complia	ance/ Inci	dents or Repeat Complaints			
to DPHI and are discusse No i	ERs cover d below fo ncidents w	of FPS, Sydney Metro now pro ing complaints related to rema or the respective projects, when vere reported to the ER during iances reported to the ER during	ining construction works. Ke re applicable or under respec the reporting period.	y or repeat items of note	
Audits					
SM	Independent Audit occurred in February 2025 for SWM3				
Looking Forward – Core Focus Areas					
SM	Collaborating with MTR and MTS to ensure the required documents are ready for Dynamic Testing and the First Passenger Service.				



5. Statement of Limitations

Healthy Buildings International (HBI) has prepared this report in accordance with the requirements of Condition A24(I) of the Sydney Metro Condition A26(j) of the Sydney Metro Conditions of Approval (CSSI 17_8256). The report is for the sole purposes of Department of Planning, Housing and Infrastructure (DPHI) and Sydney Metro. It has been prepared based on generally accepted practices and standards at the time it was prepared. No other warranty, expressed or implied, is made as to the professional advice included in this Report. This report did not assess any aspects relating to safety.

Where the Report indicates that information has been provided to HBI by third parties, HBI assumes no liability for any inaccuracies in or omissions to that information.

This Report was prepared based on the conditions encountered and information reviewed for the period of reporting. HBI disclaims responsibility for any changes that may have occurred after this time.

This Report should be read in full. No responsibility is accepted for use of any part of this report in any other context or for any other purpose or by third parties. This Report does not purport to give legal advice. Legal advice can only be given by qualified legal practitioners.

Except as required by law, no third party may use or rely on this Report unless otherwise agreed by HBI in writing. Except as specifically stated in this section, HBI does not authorise the use or findings of this Report by any third party.

To the extent permitted by law, HBI expressly disclaims and excludes liability for any loss, damage, cost or expenses suffered by any third party relating to or resulting from the use of, or reliance on, any information contained in this Report. HBI does not admit that any action, liability, or claim may exist or be available to any third party.