ACOUSTICS ADVISOR MONTHLY REPORT SYDNEY METRO WEST (SSI 10038 and SSI 192380571)

| For period: | January 2024 | Authorisation: | Dave Anderson, Acoustics Advisor |
|----------------|-----------------|----------------|----------------------------------|
| Prepared by: | Dave Anderson | | |
| Date of issue: | 7 February 2024 | | |

| Acoustics Advisor | Alternate Acous | tics Advisor(s) |
|---|--------------------|------------------------|
| Dave Anderson | Larry Clark, David | Hanson and Sav Shimada |
| | | |
| Document review | | |
| Document | Reviewed | Endorsed / approved |
| Central Tunnelling Package (CTP), AFJV | | |
| AFJV approved OOHW Permits | Υ | N/A |
| Bi-Annual Construction Monitoring Report Dec 2022 - June 2023 | Υ | |
| CNVMP Rev 11 | In progress | |
| Western Tunnelling Package (WTP), GLC | | |
| Construction Noise and Vibration Management Plan, rev G | Υ | 10/1/24 |
| GLC verification monitoring reports | Υ | N/A |
| Westmead Utilities Relocation (WUR), Quickway | | |
| OOH permit 003, rev 1 | Y | 18/01/2024 |
| Eastern Tunnelling Package (ETP), JCG ¹ | | |
| JCG verification monitoring reports | Υ | N/A |
| The Bays DNVIS Rev 3 | In progress | |
| Hunter Street DNVIS rev 1 | In progress | |

| Date | Location(s) | Details | |
|------------|--|---|--|
| 15 January | Westmead: Utilities Relocation scope (Phase H) | David Hanson OOHW Inspection | |
| | Good practice – movable noise barrier around concrete sawing, sawing completed before 10pm, battery lighting towers. | | |
| 16 January | Sydney Olympic Park, North Strathfield, Burwood North and Five Dock (Phase B2) | Larry Clark attended an OOH inspection (approx. 9pm to 1130pm). Representatives of Dept of Planning Compliance in attendance. | |
| | No noisy works seen or heard at SOP, NST, FDK (respite provided). Some low-level noise from activities within the FDK shaft / tunnel / station box excavation just barely audible on the landing outside the library at FDK west. Road plates in second avenue observed to be fixed and well-treated to minimise noise. No noise audible from FDK east shed. | | |
| | Noisy OOHWs at BWT – CCTV inspections Burwood Rd, and OS plant crane removal from south shaft site. Considerate crew behaviour noted throughout. Only non-tonal alarms heard; no loud radios heard; no excessive or unnecessary shouting or signalling with horns heard. | | |
| 17 January | WTP: Clyde Dive, MSF west and east, Rosehill (Phase F) | Larry Clark joined ER inspection and witnessed location of compressors and location for tower crane at Clyde Dive | |
| | No issues. | | |

Acoustic Studio: 202401 monthly AA report SMW January 24.docx

- 1

¹ Sydney Metro West Concept and Stage 1 (SSI 10038), Sydney Metro West Stage 2: Bays to Sydney CBD (SSI 19238057) shown in italics

| 23 January | ETP Pyrmont (Phase G2) | Dave Anderson joined ER inspection and witnessed noise monitoring of tower crane at complainant's premises |
|------------|--|--|
| | Tower crane not operating at time of visit to complainant's premises so follow up arranged for next day. Location shielded from other parts of the Pyrmont site; baseline levels 56dBL _{A90} and 59dBL _{Aeq} . Intermittent noise audible from Harbourside construction site, typically 56 to 58dBA. | |
| 23 January | WTP Parramatta, Westmead (Phase F); WUR Westmead (Phase H) | Larry Clark attended OOH inspection 8pm to 9.45pm |
| | One tonal alarm on EWP heard briefly at PTA – GLC investigating. No signalling with horns during spoil loadout at PTA – successful toolbox training. | |
| 24 January | Pyrmont incl. monitoring at resident – 50 Murray St (Phase G2) | David Hanson witnessed ETP monitoring at level 9 apartment. |
| | Diesel tower crane clearly audible at times from apartment, noise levels up to around 61dBA. Generator at base of crane clearly audible from receivers closer to the site. | |
| 30 January | Pyrmont and Hunter Street (Phase G2) | Dave Anderson joined ER inspection |
| | Real time monitoring data requested from Pyrmont West. | |
| | Demolition methodology discussed at Hunter Street. | |

| Meeting | | |
|-----------------------|----------------------------|--|
| Date | With | Purpose |
| 16, 23, 30 January | Sydney Metro, JCGJV, ER | Weekly environment meeting, ETP |
| 8, 15, 22, 29 January | AFJV, Sydney Metro, ER | Environment meeting, CTP |
| 10, 24 January | Sydney Metro, GLC, ER | Environment meeting, WTP |
| 16 January | DPE, ER | Monthly meeting with DPE compliance |
| 15 January | Sydney Metro, GLC, ATC | Fortnightly works status |
| (Not held in January) | DPE, Sydney Metro, ER, AA | Monthly meeting with DPE |
| 11, 25 January | Sydney Metro, Quickway, ER | Westmead Utilities Scope – Environment meeting |

| Noise and vibration issues, incidents, recommendations | | |
|--|---|--|
| Date | Contract / Location and details | |
| Ongoing | OOH compressor noise at Westmead exceeding NML – GLC report under review. | |
| Ongoing | JCG investigating noise from diesel tower crane at Pyrmont East. | |

| Examples of good practice in noise and vibration management | |
|---|---|
| Date | Contract / Location and details |
| 15 January | Westmead Utility Relocation, Quickway: Movable noise blankets erected around concrete sawing on road, ongoing use of battery lighting towers. |
| 23 January | No signalling with horns during spoil load-out at Parramatta – successful toolbox training. |

Ongoing and upcoming noise and vibration risks

ETP:

- Initial excavation (without acoustic sheds) starting at Pyrmont sites
- Structural demolition underway at Hunter Street sites

CTP:

• Tunnelling ground borne noise and vibration

WTP:

• Tunnelling ground borne noise and vibration

WUR:


• Night works now underway under OOHW Permits 002 (Bailey St) and 003 (Hawkesbury Rd). Note: mainly 003 until end Feb (design issue at cnr Hassall and Bailey).

Noise and vibration complaints

9 noise and vibration complaints attributed to Sydney Metro during January:

- 1 from Westmead regarding noise from heavy vehicles during standard hours
- 1 from North Strathfield regarding OOH utilities work
- 4 from Five Dock regarding, including 3 relating to OOH noise and 1 to standard hours
- 3 from Pyrmont² regarding standard hours noise from Pyrmont sites

Note: The chart shows noise and vibration (NV) complaints in standard hours and out of hours (OOH) periods. Some complaints relate to both time periods so the total number of NV complaints may be less than the sum of standard and OOH complaints.



² Sydney Metro West Concept and Stage 1 (SSI 10038), Sydney Metro West Stage 2: Bays to Sydney CBD (SSI 19238057) shown in italics